Spanish Fork, Utah April 15, 1943

Mr. Ed. H. Watson State Engineer State Capitol Bldg. Salt Lake City. Utah



Dear Sir:

On April 12, Mr. Monson of your office Mr. L.P. Thomas of the Spanish Fork River Committee Mr. Bert Oberhansley of the Clanton Irrigation Co. and myself made an inspection of the headgates and measuring devices on the Spanish Fork River Canyon district.

By a suggestion of Mr. Monson I am you a list of the turnouts that need repair. (according to our judgment) and the names and addresses of the men responsable for each turnout.

Mitchell Ditch ----- Need Weir repaired
Sunny Slope Ditch ----No measuring device Need Weir
Clinton Irrigation Co.
Mr. Bert Oberhansley
Birdseye, Utah

Aggie Ditch
Crab Ditch ----No measuring device Need Weir
Mr. Selby Dixon
Payson, Utah

R.L.Mitchell Ditch -- Need present Weir repaired R.L.Mitchell Birdseye, Utah

Floyd Gardner Ditches Need Weirs Floyd Gardner Birdseys.Utah

Simmons Ditches: Simmons Crab --- No Measureing device -- Need Weir 11 11 11 Simmons East ---Need Weir 77 ŧ. Simmons West ---Need Weir 11 Simmons Lower --11 Need Flume Mr. Max Depue

Collet Ditch ---- Need Weir Ernest Mitchell Birdseye, Utah

Thistle, Utah

George Siler Ditch ---- Need present Weir repaired
Nr. George Siler
Birdseye, Utah

Morrison Ditch --Noumeasureing device Meed Weir Jones Upper Ditch 77 11 7. 11 FF Jones Lower Ditch 17 Spencer East Ditch " 11 17 7777 11 11 Spencer West Ditch "

> Mr. R.L.Mitchell Birdseye, Wtah

Mill Ditch No measuring device Need Weir Mr. John Oberhansley Bpanish Fork. Utah

W.A.Pace Ditch Need Flume Mr.W.A.Pace Spanish Fork, Utah

A. L. Pace
Thistle, Utah

I think if these waterusers were given a letter from your office on this matter and ask to have these turnouts put in shape it would help considerably.

Very truly yours

Wayne Francis Water Commissioner

Spanish Fork. Ut.h